

APPENDIX F:

November 2021 & May 2022

Monitoring Survey Drawings


This appendix contains reduced versions of the survey drawings produced by McKim and Creed, Inc.¹ for the November 2021 (beach profiles only) and May 2022 (beach profiles and borrow site) Bald Head Island monitoring surveys.

¹ McKim & Creed, Inc.; 243 North Front Street; Wilmington, NC 28401

-- *This page intentionally left blank* --

November 2021 Drawings











-- *This page intentionally left blank* --


May 2022 Drawings











JOB NUMBER:	0074-008
CAD NUMBER:	0074-008
CAD TITLE:	EXISTING CONDITIONS HYDROGRAPHIC SURVEY
CAD DATE:	05/20/2022
DATE:	05/20/2022
DRAWN BY:	W. J. CREED
CHECKED BY:	W. J. CREED
DATE:	05/20/2022
SCALE:	1" = 200'
SHEET:	1 OF 1

JAY BIRD SHOAL BORROW AREA
 FOR
THE VILLAGE OF BALD HEAD ISLAND
 EXISTING CONDITIONS HYDROGRAPHIC SURVEY
 VILLAGE OF BALD HEAD ISLAND, BRUNSWICK COUNTY, NORTH CAROLINA
 MAY 20, 2022 SCALE 1" = 200'

MAXIMUS & CREED
 243 NORTH FRONT STREET
 WILMINGTON, NORTH CAROLINA 28401
 TELEPHONE (910) 442-1848
 FAX (910) 251-8282
 NORTH CAROLINA LICENSE NUMBER: R-1222

- NOTES:**
1. EXISTING CONDITIONS ARE SHOWN AS THEY WERE OBSERVED BY THE SURVEYING ENGINEER IN THE FIELD. NO OTHER DATA OR INFORMATION WAS USED IN THE PREPARATION OF THIS SURVEY.
 2. EXISTING CONDITIONS ARE SHOWN AS THEY WERE OBSERVED BY THE SURVEYING ENGINEER IN THE FIELD. NO OTHER DATA OR INFORMATION WAS USED IN THE PREPARATION OF THIS SURVEY.
 3. EXISTING CONDITIONS ARE SHOWN AS THEY WERE OBSERVED BY THE SURVEYING ENGINEER IN THE FIELD. NO OTHER DATA OR INFORMATION WAS USED IN THE PREPARATION OF THIS SURVEY.
 4. EXISTING CONDITIONS ARE SHOWN AS THEY WERE OBSERVED BY THE SURVEYING ENGINEER IN THE FIELD. NO OTHER DATA OR INFORMATION WAS USED IN THE PREPARATION OF THIS SURVEY.
 5. EXISTING CONDITIONS ARE SHOWN AS THEY WERE OBSERVED BY THE SURVEYING ENGINEER IN THE FIELD. NO OTHER DATA OR INFORMATION WAS USED IN THE PREPARATION OF THIS SURVEY.
 6. EXISTING CONDITIONS ARE SHOWN AS THEY WERE OBSERVED BY THE SURVEYING ENGINEER IN THE FIELD. NO OTHER DATA OR INFORMATION WAS USED IN THE PREPARATION OF THIS SURVEY.
 7. EXISTING CONDITIONS ARE SHOWN AS THEY WERE OBSERVED BY THE SURVEYING ENGINEER IN THE FIELD. NO OTHER DATA OR INFORMATION WAS USED IN THE PREPARATION OF THIS SURVEY.
 8. EXISTING CONDITIONS ARE SHOWN AS THEY WERE OBSERVED BY THE SURVEYING ENGINEER IN THE FIELD. NO OTHER DATA OR INFORMATION WAS USED IN THE PREPARATION OF THIS SURVEY.
 9. EXISTING CONDITIONS ARE SHOWN AS THEY WERE OBSERVED BY THE SURVEYING ENGINEER IN THE FIELD. NO OTHER DATA OR INFORMATION WAS USED IN THE PREPARATION OF THIS SURVEY.
 10. EXISTING CONDITIONS ARE SHOWN AS THEY WERE OBSERVED BY THE SURVEYING ENGINEER IN THE FIELD. NO OTHER DATA OR INFORMATION WAS USED IN THE PREPARATION OF THIS SURVEY.